## GRANT COUNTY

Planning Unit 041: AML Printout #559: T134N, R87W, Section 10, SW

Additional Legal Location: None

Name: Owner:

McDowell Mine G. McDowell

Category: No data

Type: Underground

Thickness

Overburden: Coal Seam: Mined: Source:

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

A 1923 WCB map indicates that the McDowell Mine was located at T134N, R87W, Section 10, SW. The mine was an underground mine, operated by the Hanson Bros.; however, no listings were noted for this mine in SEBR or CMID reports and no additional data was noted for a McDowell Mine or for other mines at this location.

Descriptive information pertaining to this mine is included in:

[source:year(pages)]

WCB Map: 1923

Notes:

None

Sources (primary and secondary):

WCB:1923